


SPROCKET DRIVE WRENCH JOSHUA BRANDON FOWLER				
O O O O O O O O O O O O O O O O O O O		BBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBB	E Contraction of the Contraction	
FIGURE: 3	TOP VIEW		100000	
DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1' = 2' 1 EACH/ASSEMBLY REQ'D	200	18 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	
Acc	ess		***************************************	
Covers			***************************************	
(5)	(4)	Drive Belt	2000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
FIG: 5	FIG: 5a		e error	
FIGURE: 5&5a	FIG: 5-TOP VIEW FIG: 50-ELEVATION VIEW	FIGURE: 4	TOP VIEW	
DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1' = 1' 1 EACH/ASSEMBLY REQ'D	DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1" = 1" 1 EACH/ASSEMBLY REQ'D	
Drive Bel	t Linkage	Drive	Belt	

SPROCKET DRIVE WRENCH JOSHUA BRANDON FOWLER				
FIGURE: 686a	FIG: 6a	FIG: 7 FIGURE: 7&7a	FIG: 7a FIG: 5-TOP VIEW FIG: 50-ELEVATION VIEW	
DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1' = 1' 1 EACH/ASSEMBLY REQ'D	DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1' = 1' 1 EACH/ASSEMBLY REQ'D	
Drive-End Sprocket		Fastener-End Sprocket		
FIG: 8	FIG: 8a			
FIGURE: 8&8a	FIG: 5-TOP VIEW FIG: 50-ELEVATION VIEW			
DATE: JANUARY 14, 2004 BY: JBF	SCALE: 1' = 1' 1 EACH/ASSEMBLY REQ'D			
Locking Device				



SPROCKET DRIVE WRENCH JOSHUA BRANDON FOWLER




FIGURE: 10 TOP VIEW SCALE: 1" = 2" DATE JANUARY 14, 2004

BY

Sectional Cutaway

1 EACH/ASSEMBLY REQ'D




FIGURE: 11 SDUTHWEST ISOMETRIC SCALE: not to scale DATE: BY: JANUARY 14, 2004 1 EACH/ASSEMBLY REQ'D

Section Cutaway